

OvisLink Bluetooth Headset

Quick Instruction

Charge before use

1. Connect the headset's USB port to an USB cellphone charger or a computer's USB port with the come with USB cable.
2. The battery LED on the headset will turn Red.
3. Once the battery fully charged the battery LED turns Green. And the Green LED will turn off after.

Headset Power Switch

- Slide to "I" side to turn on the headset. The battery LED will flash Green. It will turn Green a few times then off.
- Slide to "O" side to turn the headset off. The battery LED will flash Green then off.

Battery LED

- Red when battery low
- Red when charging battery
- Flash Green then off when turn power on
- Turn Green periodically, after connected to a device

Pairing

1. Turn on the headset
2. Press and hold the multi function key for 4 to 6 seconds.
3. The Bluetooth LED flashing blue indicates the headset is in pairing mode.
4. Find "OvisLink SBL3 HT" or "OvisLink DBL4 HT" on your device and click to connect it.

Bluetooth LED

- Flash blue when headset in pairing mode

Headset volume

- Press the + key to increase the volume
- Press the – key to decrease the volume
- You may also adjust the headset volume on the connected device

Package Include

- One OvisLink Bluetooth headset
- One USB cord

- See headset detail diagrams on next page

